



Helping Retailers Grow Profitably



Portable Verifier PV2000 User's Guide

How to Use the PV2000 Portable Verifier?

- Push and hold the button in. The PV2000 should make three quick beeps to let you know it is working. If the button is released, the PV2000 will turn off.
- If it does not beep when turned on, the battery may need to be replaced. (See *How to Replace Batteries Section*)
- While maintaining the button depression, slowly sweep the unit five to ten centimeters (two to four inches) from the possible location of the tag. An audible tone and flashing red light confirms the presence of the tag.



Description and Function of Lights During Unit Activation.

- The RED light flashes when there is a RF Tag or Hard Tag present.
- The GREEN light indicates power to the unit when button is pushed in.
- The AMBER light indicates low battery and the battery should be changed at this time. (See *How to Replace Batteries Section*)



How to Replace the Batteries?

- Remove the single screw on the bottom of the unit, and slide off the plastic shell.
- Pull battery from battery compartment and place new one in.
- The PV2000 uses a standard 9 Volt Battery.

